



**INSPECTION REPORT**

3901 cust\_id  
315284 insp\_id  
2203 site\_id

**ABILENE ZOOLOGICAL SOCIETY**

**Customer ID: 3901**

**Certificate: 74-C-0079**

**Site: 001**

**ABILENE ZOOLOGICAL SOCIETY**

**Inspection**

**Type: ROUTINE INSPECTION**

**Date: DEC-19-2007**

2070 ZOO LANE  
ABILENE, TX 79602

**3.75 ( a )**

**HOUSING FACILITIES, GENERAL.**

STRUCTURE: CONSTRUCTION. HOUSING FACILITIES FOR NONHUMAN PRIMATES MUST BE DESIGNED AND CONSTRUCTED SO THAT THEY ARE STRUCTURALLY SOUND FOR THE SPECIES OF NONHUMAN PRIMATES HOUSED IN THEM. THEY MUST BE KEPT IN GOOD REPAIR, AND THEY MUST PROTECT THE ANIMALS FROM INJURY, CONTAIN THE ANIMALS SECURELY, AND RESTRICT OTHER ANIMALS FROM ENTERING. AT THE TIME OF THIS INSPECTION, THE FASCIA AROUND THE SPIDER MONKEY AND JAGUAR EXHIBITS IS DETERIORATING AND IS IN REACH OF THE SPIDER MONKEYS. TO BE CORRECTED BY: JUNE 1, 2008.

**3.126 ( b )**

**FACILITIES, INDOOR.**

VENTILATION. INDOOR HOUSING FACILITIES SHALL BE ADEQUATELY VENTILATED BY NATURAL OR MECHANICAL MEANS TO PROVIDE FOR THE HEALTH AND TO PREVENT DISCOMFORT OF THE ANIMALS AT ALL TIMES. SUCH FACILITIES SHALL BE PROVIDED WITH FRESH AIR BY MEANS OF WINDOWS, DOORS, VENTS, FANS, OR AIR-CONDITIONING AND SHALL BE VENTILATED SO AS TO MINIMIZE DRAFTS, ODORS, AND MOISTURE CONDENSATION. AT THE TIME OF THIS INSPECTION, THERE WERE BROKEN, NON-FUNCTIONAL WINDOWS IN THE TEXAS AND ZEBRA BARN. TO BE CORRECTED BY: JUNE 1, 2008.

Prepared By:

*Jeanne Kjos Am*  
JEANNE KJOS, V.M.D., USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER, Inspector ID: 4013

Received By:

*Bill Baker*  
BILL BAKER

Title: DIRECTOR

Date:

DEC-19-2007

Date:

DEC-19-2007



**INSPECTION REPORT**

**ABILENE ZOOLOGICAL SOCIETY**

Customer ID: 3901  
Certificate: 74-C-0079

Site: 001  
ABILENE ZOOLOGICAL SOCIETY

2070 ZOO LANE  
ABILENE, TX 79602


Inspection  
Type: ROUTINE INSPECTION  
Date: AUG-29-2007

**3.125 ( a )  
FACILITIES, GENERAL.**

STRUCTURAL STRENGTH. THE FACILITY MUST BE CONSTRUCTED OF SUCH MATERIAL AND OF SUCH STRENGTH AS APPROPRIATE FOR THE ANIMALS INVOLVED. THE INDOOR AND OUTDOOR HOUSING FACILITIES SHALL BE STRUCTURALLY SOUND AND SHALL BE MAINTAINED IN GOOD REPAIR TO PROTECT THE ANIMALS FROM INJURY AND TO CONTAIN THE ANIMALS. FOR EXAMPLE, THERE ARE THREE DIFFERENT LOCK SYSTEMS TO GAIN FULL ACCESS TO THE BEAR FACILITY. THIS ISSUE WAS NOTED THROUGHOUT THE ZOO. AN IMPROVED ANIMAL ENCLOSURE ACCESS SYSTEM MUST BE DEVELOPED TO FACILITATE DAILY HUSBANDRY ROUTINES AND EMERGENCY PROCEDURES. TO BE CORRECTED BY: NOVEMBER 30, 2007.

**3.126 ( d )  
FACILITIES, INDOOR.**

PERIMETER FENCE. ON OR AFTER MAY 17, 2000, ALL OUTDOOR HOUSING FACILITIES MUST BE ENCLOSED BY A PERIMETER FENCE THAT IS OF SUFFICIENT HEIGHT TO KEEP ANIMALS AND UNAUTHORIZED PERSONS OUT. FENCES LESS THAN 8 FEET HIGH FOR POTENTIALLY DANGEROUS ANIMALS MUST BE APPROVED IN WRITING BY THE ADMINISTRATOR. AT THE TIME OF THIS INSPECTION, A NEW SECTION OF THE PERIMETER FENCE BY THE NEW ZOO ENTRANCE FACILITY IS 6 FEET TALL. THE PERIMETER FENCE MUST BE A MINIMUM OF 8 FEET TALL. TO BE CORRECTED BY: NOVEMBER 30, 2007.

Prepared By:   
JEANNE KJOS, V.M.O. , USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER , Inspector ID: 4013

Date:  
AUG-29-2007

Received By:   
BILL BAKER

Title: ZOO DIRECTOR

Date:  
AUG-29-2007



3901 cust\_id  
315023 insp\_id  
2203 site\_id

**INSPECTION REPORT**

**ABILENE ZOOLOGICAL SOCIETY**

Customer ID: 3901

Certificate: 74-C-0079

Site: 001

ABILENE ZOOLOGICAL SOCIETY

2070 ZOO LANE  
ABILENE, TX 79602

Inspection

Type: ROUTINE INSPECTION

Date: NOV-21-2006

NO NON-COMPLIANCES IDENTIFIED THIS INSPECTION.

Prepared By: *Jeanne Kjos*  
JEANNE KJOS, V.M.O. , USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER , Inspector ID: 4013

Date:  
NOV-21-2006

Received By: *Doug Hotle*  
DOUG HOTLE

Title: ZOO CURATOR

Date:  
NOV-21-2006



**INSPECTION REPORT**

3901 cust\_id  
188979 Insp\_id  
2203 site\_id

**ABILENE ZOOLOGICAL SOCIETY**

Customer ID: 3901

Certificate: 74-C-0079

Site: 001

ABILENE ZOOLOGICAL SOCIETY

2070 ZOO LANE  
ABILENE, TX 79602

Inspection

Type: ROUTINE INSPECTION

Date: AUG-22-2006

NO NON-COMPLIANCES IDENTIFIED THIS INSPECTION.

Prepared By: *Jeanne Kjos*  
JEANNE KJOS, V.M.O. , USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER , Inspector ID: 4013

Date:  
AUG-22-2006

Received By: *Jeff Bullock*  
JEFF BULLOCK

Title: DIRECTOR

Date:  
AUG-22-2006